

Additions to the Snagging List

Date: 9. Aug 2009

Participants: Axel

Topic: Additions to the Preliminary Snagging List dated 6. August 2009

1. The 3 way lock does not properly work
 - a. Outside door next to storage room: the fly screen does not roll up properly
2. Hardwood floor Dressing Room:
 - a. On several parts of the floor it is hollow and the glue down is not applied properly. The entire floor needs to be checked for hollow spots
3. Bedroom Roller Shutter:
 - a. The roller shutter has major scratches from the outside
4. The roller shutter is missing pieces. When the shutter is all the way closed, sun is shining in at the top
5. Water facet needs to be implemented on the back balcony, it is leaking water
6. Bathroom: The fly screens do not roll up properly
7. General outside:
 - a. The satellite dish needs to be placed and installed properly
 - b. The water pump is very noisy when water is taken out. Sound isolation needs to be applied
 - c. The windows in the storage room above Axels apartment need to be cleaned and lights need to be attached
8. Entrance doors car port and main entrance: A stopper is missing as well as a lock of some kind
9. The automatic sensor light at the car pool needs to be adjusted. The light turns off to quickly and the sensor is pointed at the wrong direction

Pool

1. We are losing water in a big way (until 8. August 40 Tons). The neighbour detected the problem and turned off the main water supply. I found that a pipe in the lower part of the overflow pool is not connected